

Seal Beach WAVE



Broken Angle Meter Stop Valve Replaced

During routine work, Utilities staff recently came across a broken meter angle stop valve. This valve, located inside the meter box, is an important part of our water system—it serves as the shutoff point that controls water flow to the residential or commercial property side.

To address the issue, crews carefully removed the meter box, replaced the damaged angle stop valve, and reinstalled the box. With the new valve in place, water service to the property can now be safely and reliably controlled as needed.

