

Seal Beach WAVE



Upgrading Equipment for Reliable Water Service

The Utilities team recently replaced a broken $\frac{3}{4}$ -inch meter angle stop to ensure reliable and accurate water service for residents. The angle meter stop, a key component that controls water flow to the meter, was damaged and required prompt replacement. In addition to making repairs, the Utilities Division continues to upgrade and modernize the equipment used to read water meters. These improvements enhance efficiency, accuracy, and data collection, allowing staff to respond to service issues more effectively.

